

3500 Printers
ERROR MESSAGE

These are the instructions for changing to I/O timeout on the 3500 printer.

On the control panel of the printer:

Press menu

Press the down key until *Configure Device* is highlighted, then press the green check mark

Press the down key until *I/O* is highlighted, then press the green check mark

Press the down key until *I/O Timeout* is highlighted, then press the green check mark

Press the up key to increase the timeout to 60 seconds, then press the green check mark

Press menu and try to print